CESSNA FIBERGLASS REPLACEMENT PARTS

CESSNA 177/180/185/188

CESSNA FIBERGLASS REPLACEMENT PARTS FOR 177

What Makes These Composite Parts Such An Excellent Value?

- * Stronger than factory originals with no weight increase.
- Easily repaired with locally available fiberglass kits if ever damaged.
 Exact replacements of original equipment means easy installation.
- * Money back guarantee if not completely satisfied!

STABILATOR TIPS

Here are some of our most popular items. These tips take a good deal of stress in just normal flying circumstances. They're also frequent victims of ramp rash. The original plastic simply can't stand up to the task as well as fiberglass replacements from Stene Aviation. Plus, if these parts ever do withstand damage, they're easily repaired with readily available fiberglass repair kits from you local automotive parts store.

Photo	Description	Part No.	Price
	177 Stabilator Tip (All) (SA- 1732024-1)	05-03744	

<u>RUDDER & VERTICAL TOPS</u>

Photo	Description	Part No.	Price
	177 Rudder Top (All) (SA- 1733009-2)	05-03841	
	177 Vertical Top (All) (SA- 1731009-4)	05-03840	

GEAR LEG FAIRINGS

Photo	Description	Part No.	Price
1	177 Upper Gear Leg (All) RH (SA-1741005-44)	05-03846	-
	177 Upper Gear Leg (All) LH (SA-1741005-43)	05-03845	
	177 Brake Fairings 1972-'74 RH (SA-0741634-14)	05-03848	
	177 Brake Fairings 1972-'74 LH (SA-0741634-13)	05-03847	
	177 Brake Fairings 1975&on RH (SA-0741641-10)	05-03849	
3	177 Brake Fairings 1975&on LH (SA-0741641-11)	05-03850	

WHEEL PANTS

Replace your original plastic wheel pants with high quality and durable fiberglass replacements. All wheel pants come with a 2" access plug for checking tire pressure. Original hardware is required for mounting.

Photo	Description	Part No.	Price
0	177 Wheel Pant 1975&on RH (SA-0541223-16)	05-03728	
	177 Wheel Pant 1975&on LH (SA-0541223-17)	05-03729	
	177 Nose Wheel Pant 1975&on (SA-0543079-3)	05-03730	

CESSNA FIBERGLASS REPLACEMENT PARTS FOR 180/185

ELEVATORS & STABILIZERS

Here are some of our most popular items. These tips take a good deal of stress in just normal flying circumstances. They're also frequent victims of ramp rash. The original plastic simply can't stand up to the task as well as fiberglass replacements from Stene Aviation. Plus, if these parts ever do withstand damage, they're easily repaired with readily available fiberglass repair kits from you local automotive parts store.

Photo	Description	Part No.	Price
	180&185(all) Horizontal Tip (SA-0732613-1)	05-03779	

180/185 CONT.

STRUT CUFFS

Here's an unbeatable item for renovating your Cessna; a set of replacement strut cuffs. Order just one cuff to replace a damaged original, or get

Photo	Description	Part No.	Price
	180 Strut Cuff Upper RH (SA- 0723605-4)	05-03774	
	180 Strut Cuff Upper LH (SA- 0723605-3)	05-03773	
	180 Strut Cuff Lower RH (SA- 0723605-2)	05-03772	
	180 Strut Cuff Lower LH (SA- 0723605-1)	05-03771	

RUDDER & VERTICAL FIN CAPS

These parts are a snap to replace on most planes. Please note, indicate if you have a straight tail or a swept tail. It is also important to let us know if your fin cap needs to accommodate a strobe or beacon, and if so, if the light is front-mounted or center-mounted.

Photo	Description	Part No.	Price
	180 (all) Vertical Fin (no beacon) (SA-0731000-200)	05-03781	
	180 (all) Vertical Fin (small bea- con)(SA-0731019-1)	05-03782	
	Fin (sm. beacon) (SA-0/31019-2)	05-03787	
	185 Vertical Fin (no beacon) (SA-0742025-1)	05-03788	
	180(all) Vertical Fin (large beacon) (SA-0700031-2)	05-03789	
A	185(all) Vertical Fin (large beacon) (SA-0731015-1)	05-03790	

GEAR LEG AND BRAKE FAIRINGS

These are excellent items for replacing worn plastic originals. Your fiberglass replacements will be more durable with an improved finish over the original plastics.

Photo	Description	Part No.	Price
	180/185 & oversize Brake Fair- ing RH(SA-0741059-2)	05-03804	
0	180/185 & oversize Brake Fair- ing LH(SA-0741059-1)	05-03805	

WING & DORSAL TIPS

Wing tips are a common victim of hanger and ramp rash. Maybe you thought the plane was going to clear those doors as you wheeled it back into the hanger...the first indication that you were wrong was that grating sound as the wing tip met metal. Here's the solution: replacement fiber-

Photo	Description	Part No.	Price
	180 Wing Tip (staight tip)- 1955- '67 (SA-0723615-200)	05-03797	
	180/185 Wing Tip (small droop) 1969-'72 LH(SA-0523565-29)	05-03726	ŧ
	180/185 Wing Tip (small droop) 1969-'72 RH(SA-0523565-30)	05-03727	
	180/185 Large Wing Tip 1962-'69 LH(SA-1223000-7)	05-03795	
	180/185 Large Wing Tip 1962-'69 RH(SA-1223000-8)	05-03796	
	180/185 Wing Tip (small droop) 1973&on LH(SA-0723200-5)	05-03762	
	180/185 Wing Tip (small droop) 1973&on RH(SA-0723200-6)	05-03761	