

OVERHAULED INSTRUMENTS

OVERHAULED INSTRUMENTS

These instruments are overhauled and certified at our affiliated instrument repair facility and are available on an outright purchase basis (stock permitting). For outright purchase, you will be billed the purchase price plus core charge. Core charge is credited upon return of acceptable core. We can also overhaul your instrument at the price shown, and no core charge will be billed. Allow 2-3 weeks for overhaul of your instrument. If in stock, outright purchases can ship within 2 days. Warranty details are included with the instrument.

To send in your instrument for overhaul or to return a core, please contact Aircraft Spruce Customer Service in advance for an RMA number and then ship instrument to Aircraft Spruce East in Georgia.

Model	Description	Core Charge	PN	Price
Overhauled 5000 Series Standard	Attitude Gyro	.	10-03111	.
Overhauled 4000 Series Standard	Directional Gyro	.	10-03114	.
Overhauled 1U367-002-2	Attitude Gyro	.	10-03117	.
Overhauled 1U367-006-6	Attitude Gyro	.	10-03118	.
Overhauled 5934 Series	Altimeter	.	10-03119	.
Overhauled 5950 Series	Altimeter	.	10-03120	.
Overhauled 371 Series	Altimeter	.	10-03121	.
Overhauled 671 Series	Altimeter	.	10-03122	.
Overhauled 7000 Series	VSI (Vertical Speed Indicator)	.	10-03123	.
Overhauled 8000 Series	Airspeed Indicator	.	10-03125	.
Overhauled 8025 Series	Airspeed Indicator	.	10-03126	.
Overhauled 8030 Series	Airspeed Indicator	.	10-03127	.
Overhauled 8040 Series	Airspeed Indicator	.	10-03128	.
Overhauled 8100 Series	Airspeed Indicator	.	10-03129	.
Overhauled 8125 Series	Airspeed Indicator	.	10-03130	.
Overhauled 8130 Series	Airspeed Indicator	.	10-03131	.
Overhauled 8140 Series	Airspeed Indicator	.	10-03132	.
Overhauled EA-5171 thru EA-5176	Airspeed Indicator	.	10-03133	.

IN